

Asset Number	Description	Model Number	Vehicle Year/Make/Model	VIN# / Serial #	Miles (Estimated)	Plate #	Location	Inspection Form	Title	Condition
7688	Vehicle		2013 Dodge Charger	2C3CDXAG8DH545486	145,097	17313-V	Surplus Lot	Yes	Yes	Works, fair condition. Windshield is cracked, holes in exterior from equipment removed but starts with worn tires.
7352	Vehicle		2008 Dodge Avenger	1B3LC46K98N236294	104,630	17491-V	Surplus Lot	Yes	Yes	Check engine light on needs intake manifold
7670	Vehicle		2013 Dodge Charger	2C3CDXAG9DH545478	104,114	95026-T	Surplus Lot	Yes	Yes	Paint peeling on hood, starts with a boost, and tire condtion poor. Runs and is driveable
7746	Vehicle		2013 Dodge Charger	2C3CDXAG2DH734490	128,180	69749-T	Surplus Lot	Yes	Yes	Works, fair condition. Holes in the exterior from emergency equipment removal. In good condition
7800	Vehicle		2013 Dodge Charger	2C3CDXAG32H350994	110,169	72440-V	Surplus Lot	Yes	Yes	Starts with a boost and is driveable, tires are poor and there are holes in exterior from emergency equip removal.
7801	Vehicle		2013 Dodge Charger	2C3CDXAG9EH350997	118,143	72441-V	Surplus Lot	Yes	Yes	Starts with a boost and is driveable, holes in the exterior from emergency equipment removal.
8110	Vehicle		2019 Ford PIU/Explorer	1FM5K8AR6KGA28712	199,093	20660-W	Surplus Lot	Yes	Yes	Runs and is driveable, but transmission has a bad shudder. There are scratches and dings and the windshield is chipped, but the tires are good. There are holes in the back of driver's seat, as well as A-Pillar, headliner, and the left arm rest
7803	Vehicle		2014 Dodge Charger	2C3CDXAG7EH351002	137,033	72443-V	Surplus Lot	Yes	Yes	Starts, runs, and is driveable, however needs struts and lower control arms. The tire are in fair condition, but the dash pad is cracked. There are remaining impressions from decals and holes from equipment removal.
7799	Vehicle		2014 Dodge Charger	2C3CDXAG1EH350993	119,393	72439-V	Surplus Lot	Yes	Yes	Starts with a boost and is driveable, there are general stratches and dings, but tires are good and no cracked glass. There are impressions from previous removed decals and holes to exterior from equipment removal.
7744	Vehicle		2013 Dodge Charger	2C3CDXAG4DH734488	136,457	69747-T	Surplus Lot	Yes	Yes	Runs and is driveable with a boost, there are no impressions from previous decals but has regular scratches and dings. Tires are good, and there are holes in the exterior where equipment was removed.

8062	Vehicle		2018 Dodge Charger	2C3CDXAG9JH201290	77,515	13472-W	Surplus Lot	Yes	Yes	Runs and is operable, tires are in good condition and there are no impressions from decals. There are holes to the exterior for equipment removed.
6808	Vehicle		2010 Ford Ranger	1FTKR1EE7APA44062	144,101	17471-V	Surplus Lot	Yes	Yes	Starts with a boost and is driveable, but shift indicator is broken. Tires are good, but windshield is cracked. Has a receiver hitch. Holes made from previous equipment & removal
7376	Vehicle		2008 Ford 250	1FTSX21578EE39835	92,890	95086-T	Surplus Lot	Yes	Yes	Runs and is driveable, it is operable with good tires and some dings and scratches. Impressions do remain from previous decals.
7725	Vehicle		2013 Ford Fusion	3FA6POG72DR328721	207,897	63943-V	Surplus Lot	Yes	Yes	Starts and is driveable, timing cover and oil pan do leak. There is a harsh shift when cold and a cracked winshield. Tires are good, but there are stains to seats and the headliner interior hangs down in the front.
7748	Vehicle		2013 Dodge Charger	2C3CDXAG6DH734492	123,404	69752-T	Surplus Lot	Yes	Yes	Starts with a boost and is driveable, tireds are good and no glass cracked. No impressions made from equipment removal
7971	Vehicle		2017 Ford Taurus	1FAHP2MK0HG102848	137,720	93328-V	Surplus Lot	Yes	Yes	Starts and is driveable, however there is a transmission shudder. Tires are good, there are holes in the exterior from equipment being removed.
7809	Vehicle		2014 Ford Taurus	1FAHP2MKXEG160073	77,015	17342-V	Surplus Lot	Yes	Yes	Runs and is operable, tires are fair and there are holes in the exterior where equipment was removed and standard scratches and dings
7834	Vehicle		2016 Cheverolet Impala	2G1WA5E39G1100905	109,948	79704-V	N/A	N/A	Yes	Vehicle runs well and has limited dings and scratches. Interior is also clean with no staining or major signs of damage.
7932	Vehicle		2017 Volvo Roll-Off Truck	4V5KC9EGXHN971094	426947	85994V	Surplus Lot	Yes		Works and is driveable, but needs considerable repair. Transmission needs to be totally replaced. There are normal dings, but there are chips in the windshield and the right side mirror is damaged. There are imprints from previous equipment and seats worn and torn

7742	Vehicle		2013 Dodge Charger	2C3CDXAG5DH734497	145378	TFZ5255	Surplus Lot	Yes		Starts with a boost and runs and driveable. There are regular scratches and dings, but no cracks in glass. Tires and interior are good, but there are holes on the exterior from equipment removal.
------	---------	--	--------------------	-------------------	--------	---------	-------------	-----	--	---

