


NOTES

1. THIS IS NOT A BOUNDARY SURVEY.
2. GROUND SHOTS TAKEN FOR GENERAL DRAINAGE PATTERNS ONLY- NOT A PRECISE ONE FOOT CONTOUR INTERVAL.
3. HORIZONTAL GROUND DISTANCES SHOWN HEREON.



REVISED 12/14/2002--ADDED/ROMANED ADDITIONAL LIMITS TO INTERPRETED PROTECTION BOUNDARY
 REVISED 11/16/2002--ADDITIONAL FIELD DIRECTIONAL ARROWS ADDED
 REVISED 11/17/2002--ADDITIONAL APPROXIMATE PROPERTY LINE ADDED
 REVISED 9/26/2002--ADDITIONAL SURFACE AND SUBSURFACE UTILITIES AND SHEET # OF 2
 REVISED 7/9/2002--ADDITIONAL SURVEY AREA NORTH OF MAINS CHURCH CROSSING CEDAR LAKE
 REVISED 5/26/2002--ADDITIONAL SURVEY AREA NORTH OF MAINS CHURCH CROSSING CEDAR LAKE
 REVISED 6/29/2001--DELIMITATION OF FIELD LOCATED RIDGELINE AS DETERMINED BY CHRIS BOSTIC, P.E. AND
 "CURRENT COUNTY MAP RIDGELINE" (MS-1 BW) BY KATIE JUDG, CIVIL
 40 20 0 40 80 120
 SCALE IN FEET
 SCALE: 1" = 40' MAY 19, 2021

RILEY SURVEYING, P.A.
3326 DURHAM CHAPEL HILL BLVD. STE B-100
DURHAM, N.C. 27707
919-667-0742 C-1281 Email: jcorrea@rileysurveyingpa.com